

All Fabricating Distributors must have a nonconforming material process at least equal to ISO9001:2015 clause 8.7 & 10.2 requirements in lieu of Titeflex SOP:QA 830

CURRENT ASSEMBLY PROCEDURE REVISIONS

<u>ACTIVE PROCEDURES</u>	<u>REV</u>
AP-01	Q
AP-02	F
AP-04	G
AP-06	G
AP-08	F
AP-09	S
AP-13	F
AP-14	P
AP14-1	8-11
AP14-2	8-11
AP-31	H
AP31-1	11-11
AP31-2	11-11
AP-33	H
AP-34	G
AP-36	B
AP-37	H
AP-38	F
AP-39	A
AP-40	B
AP-41	C
AP-44	B
AP-47	A
AP-48	A
AP-49	A

Copies of the current revision of these procedures are available to authorized fabricating distributors by contacting Titeflex Commercial

Updated: Monday, February 13, 2023

